Printing date 09.01.2019

Revision: 09.01.2019

SECTION 1: Identification of the substance/mixture and of the company/undertaking

• 1.1 Product identifier

Trade name: THERMELAST [®]4290

• Detailed descriptions:

® registered trademark of VACUUMSCHMELZE GmbH & Co. KG

- Information sheet no.: IB20
- Remarks for information sheet

Our semi-finished and finished products constitute manufactured articles under the terms of the REACH Regulation (EC) No. 1907/2006.

Articles are not subject to any legal obligation concerning production and distribution of material safety data sheets. The detailed information usually shown in a safety data sheet will be provided in the form of an 'Information sheet for articles' for specific alloys.

However, we expressly point out that these information sheets for articles are voluntarily produced data sheets which are not governed by the requirements of the REACH regulation.

• 1.2 Relevant identified uses of the substance or mixture and uses advised against Not applicable

- Application of the article: semi-finished products and parts
- 1.3 Details of the supplier of the information sheet
- Manufacturer/Supplier: VACUUMSCHMELZE GmbH & Co.KG Grüner Weg 37 D-63450 Hanau

datasheet@vacuumschmelze.com

- Further information obtainable from: Environmental Protection Department
- **1.4 Emergency telephone number:** Tel. no.: (**49) 6181/38-0 Emergency tel. no.: via (**49) 6181/38-0

SECTION 2: Hazards identification

- 2.2 Classification (substance or mixture) Classification according to Regulation (EC) No 1272/2008 (CLP-Regulation): Not applicable For articles there is no obligation to classify acc. to CLP -Regulation.
- 2.2 Labelling according to Regulation (EC) No 1272/2008 Labelling according to Regulation (EC) No 1272/2008 (CLP-Regulation): Not applicable

Additional VAC information: In the case of dust-producing processing, we recommend observance of the following warnings :
Hazard statements May cause an allergic skin reaction. May cause cancer by inhalation. Causes damage to organs through prolonged or repeated exposure.
Precautionary statements Do not breathe dust/fume/gas/mist/vapours/spray. Do not breathe dust/fume/gas/mist/vapours/spray. Do not eat, drink or smoke when using this product. Avoid release to the environment. Use personal protective equipment as required. In case of inadequate ventilation wear respiratory protection. Get medical advice/attention if you feel unwell. (Contd. on page 2)



for articles

Version number 2

Revision: 09.01.2019

Trade name: THERMELAST [®]4290

(Contd. of page 1)

• 2.3 Other hazards

• Results of PBT and vPvB assessment

• PBT: Not applicable.

• vPvB: Not applicable.

SECTION 3: Composition/information on ingredients

- 3.2 Chemical characterization:
- Description: Metal in compact form

• Components(composition):

The classifications given below reflect the classification of each <u>pure substance</u> respectively and are intended for information only

The legal classifications of the pure substances (harmonized classification according to substance list of the Annex VI of the CLP Regulation) got complemented, insofar as additional substance-specific information from accessible data sources (e.g. TRGS 905, toxicological studies) for health hazards and / or physical hazards are available.

CAS: 7440-02-0 EINECS: 231-111-4 Index number: 028-00	nickel Carc. 2, H351; STOT RE 1, H372; 🗘 Skin Sens. 1, H317 2-00-7	~ 42%
CAS: 7440-41-7 EINECS: 231-150-7 Index number: 004-00 RTECS: DS 1750000	beryllium Acute Tox. 3, H301; Acute Tox. 2, H330; Carc. 1B, H350i; STOT RE 1, H372; Skin Irrit. 2, H315; Eye Irrit. 2, H319; Skin Sens. 1, H317; STOT SE 3, H335	< 0.6%
NON-hazardous Ingre	edients	
CAS: 7439-89-6 EINECS: 231-096-4 RTECS: NO 4565500	iron (compact form)	rest%
CAS: 7439-98-7 EINECS: 231-107-2 RTECS: QA 4680000	molybdenum	~ 9%

• Additional information: For the wording of the listed hazard phrases refer to section 16.

SECTION 4: First aid measures

• 4.1 Description of first aid measures

• After inhalation:

If metal vapours or dusts have been inhaled:


Get the affected person out in the fresh air and call a doctor.

- After skin contact: Foreign bodies which have penetrated the skin must be removed and the wound cleaned thoroughly.
- After eye contact:

Rinse opened eye for several minutes under running water. If symptoms persist, consult a doctor.

- After swallowing: Consult a doctor if the symptoms persist.
- 4.2 Most important symptoms and effects, both acute and delayed No further relevant information available.
- Information for doctor: Beryllium, chronic lung diseases (berylliosis)
- 4.3 Indication of any immediate medical attention and special treatment needed

No further relevant information available.





for articles

Version number 2

Trade name: THERMELAST [®]4290

(Contd. of page 2)

SECTION 5: Firefighting measures

- 5.1 Extinguishing media
- Suitable extinguishing agents:
- Non-combustible.
- Extinguishing agents must be adapted to the environment.
- 5.2 Special hazards arising from the substance or mixture
- Formation of toxic smoke / fumes (metal / metal oxides) is possible during heating or in case of fire. Do not inhale fumes.
- 5.3 Advice for firefighters
- Protective equipment: No special measures required.

SECTION 6: Accidental release measures

Accidental release of dusts and vapours which are damaging to health can be ruled out.

- 6.1 Personal precautions, protective equipment and emergency procedures No special measures required.
- 6.2 Environmental precautions: No special measures required.
- 6.3 Methods and material for containment and cleaning up: No special measures required.
- 6.4 Reference to other sections
- See Section 7 for information on safe handling.
- See Section 8 for information on personal protection equipment.

See Section 13 for disposal information.

SECTION 7: Handling and storage

 7.1 Precautions for safe handling No safety precautions are necessary in the delivered form.

The appropriate industrial and environmental safety measures

must be taken for processing steps which cause dust

(see also section 8):

Ensure good ventilation/exhaustion at the workplace.

Take note of emission threshold.

• Information about fire - and explosion protection: No special measures required.

•7.2 Conditions for safe storage, including any incompatibilities

- Storage:
- Requirements to be met by storerooms and receptacles: No special requirements.
- Information about storage in one common storage facility: Not required.
- Further information about storage conditions: Not applicable
- Storage class: Not applicable
- •7.3 Specific end use(s) No further relevant information available.

SECTION 8: Exposure controls/personal protection

Additional information about design of technical facilities:

Provide suction with filtering for good airing and ventilation of the work area during processing steps which cause dust. Air return is only permitted in exceptional cases.

If industrial vacuum cleaners are used, these must have dust class H (DIN EN 60335-2-69).

Suitable breathing apparatus must be used during repair and maintenance work to suction systems, especially when changing filters (see personal safety equipment).

(Contd. on page 4)

F



for articles

Version number 2

Revision: 09.01.2019

Trade name: THERMELAST [®]4290

 e.1 Control parameters Hogredients with limit values that require monitoring at the workplace: For International Limit Values see Additional information below. 7440-02-0 nickel AGW (Germany) [Long-term value: 0.006A; 0.030E* mg/m³ [0]();AGS, 24, Sh, Y, 10*, 31* 7440-17 beryllium 7440-17 beryllium AGW (Germany) [Long-term value: 0.00006* 0.00014** mg/m³ [1]();AGS, X, 10*alveolengängig *einatembar; als Be ONELS DNELS for OSH purposes In Germany, occupational exposure limits (AGW) of the Technical Rules on Hazardous Substances (TRGS) 9 continue to constitute workplace atmospheric limit values that are binding upon employers. Should no AGW a for example no maximum workplace concentration (MAK value) of the German Research Foundation (DFG) b available, the employer must also consider the DNEL during tisk assessment. (Source: Institut für Arbeitsschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available. http://www.dguu.de/ita/gestis/gestis-dnel-list/index.jsp. 7440-02-0 nickel Inhalative [Long-term exposure - inhalation - local effects 0.05 mg/m² (Ind) Long-term exposure - inhalation - systemic effects 0.05 mg/m² (Ind) vadditional Occupational Exposure Limit Values for possible hazards during processing: Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. Additional information: The Isits valid during the making were used as basis. GESTIS International Limit Values; Berasinal protective equipment: Concel aprotective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and		(Contd. of page
For International Limit Values see Additional information below. 7440-02-0 nickel AGW (Germany) Long-term value: 0.006A; 0.030E* mg/m³ g)(10),AGS, 24, 5h, Y, 10*, 31* 7440-17-7 beryllium AGW (Germany) Long-term value: 0.00006* 0.00014** mg/m³ 1(1),AGS,X,10*alveolengångig *einatembar; als Be •NELS DNELS for OSH purposes In Germany, occupational exposure limits (AGW) of the Technical Rules on Hazardous Substances (TRGS) 9 continue to constitute workplace atmospheric limit values that are binding upon employers. Should no AGW a for example no maximum workplace concentration (MAK value) of the German Research Foundation (DFG) b available, the employer must also consider the DNEL during risk assessment. (Source: Institut für Arbeitschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available: http://www.dgu/.de/i/a/gests//gestic-dnel-liste/index.jsp. 7440-02-0 nickel Inhalation - local effects 0.05 mg/m³ (Ind) Inhalative [Long-term exposure - inhalation - local effects 0.05 mg/m³ (Ind) rthe AGW for nickel in to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. •Additional Information •The lists valid during the making were used as basis. •GESTIS International Limit Values •Additional Information <th></th> <th></th>		
7440-02-0 nickel AGW (Germany) Long-term value: 0.00064; 0.030E* mg/m³ 8(II):AGS, 24, Sh, Y, 10*, 31* 7440-41-7 beryllium AGW (Germany) Long-term value: 0.00006* 0.00014** mg/m³ 1(I):AGS, X1.0*alveolengängig *einatembar; als Be PNELs DNELs for OSH purposes In Germany, occupational exposure limits (AGW) of the Technical Rules on Hazardous Substances (TRGS) 9 continue to constitute workplace atmospheric limit values that are binding upon employers. Should no AGW a for example no maximum workplace concentration (MAK value) of the German Research Foundation (DFG) b available, the employer must also consider the DNEL during risk assessment. (Source: Institut für Arbeitschutz der Dutschen Gesetzlichen Unfallversicherung (IFA)) currer values are available: http://www.dguv.de/ifa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative [Long-term exposure - inhalation - local effects [0.05 mg/m³ (Ind) Long-term exposure - inhalation - local effects [0.05 mg/m³ (Ind) Compliance with the general dust limit values (S) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. [Compliance accentration: The HESS valid during the making were used as basis. -GESTIS International Limit Values		
AGW (Germany) Long-term value: 0.006A; 0.030E* mg/m ³ 8(II);AGS, 24, Sh, Y, 10°, 31° 7440-417 beryflium AGW (Germany) Long-term value: 0.0006° 0.00014** mg/m ³ 1(I);AGS, X, 10 *alveolengängig *einatembar; als Be 70NELS DNELS for OSH purposes In Germany, occupational exposure limits (AGW) of the Technical Rules on Hazardous Substances (TRGS) 9 continue to constitute workplace atmospheric limit values that are binding upon employers. Should no AGW a for example no maximum workplace concentration (MAK value) of the German Research Foundation (DFG) b available, the employer must also consider the DNEL during risk assessment. (Source: Institut für Arbeitsschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available: http://www.dguv.de/ifa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects 0.05 mg/m ³ (Ind) Long-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) Cog-term exposure - inhalation exposure Cog term aprocesses in the presence of atmospheric oxygen, oxidic		
[B(III):AGS, 24, Sh, Y, 10°, 31° 7440-41-7 beryllium AGW (Germany) Long-term value: 0.00006° 0.00014** mg/m³ 1(I):AGS, X, 10 *alveolengängig *einatembar; als Be DNELs for OSH purposes In Germany, occupational exposure limits (AGW) of the Technical Rules on Hazardous Substances (TRGS) 9 continue to constitute workplace atmospheric limit values that are binding upon employers. Should no AGW a for example no maximum workplace concentration (MAK value) of the German Research Foundation (DFG) b available, the employer must also consider the DNEL during risk assessment. (Source: Institut für Arbeitsschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available: http://www.dguv.de/ffa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects 0.05 mg/m³ (Ind) • Additional Occupational Exposure Limit Values for possible hazards during processing: Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. • Additional Information: • • The lists valid during the making were used as basis. • GESTIS International Limit Values: http://www.dguv.de/fia/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzei limit-values-for-chemical-agents/index.jsp • Bzeposure controls • • Personal p		
AGW (Germany) Long-term value: 0.0006* 0.00014** mg/m³ (1);AGS,X,10 *alveolengängig *einatembar; als Be PNELs DNELs for OSH purposes In Germany, occupational exposure limits (AGW) of the Technical Rules on Hazardous Substances (TRGS) 9 continue to constitute workplace atmospheric limit values that are binding upon employers. Should no AGW a for example no maximum workplace concentration (MAK value) of the German Research Foundation (DFG) b available, the employer must also consider the DNEL during risk assessment. (Source: Institut für Arbeitsschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available: http://www.dguv.de/ifa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects Long-term exposure - inhalation - systemic effects 0.05 mg/m³ (Ind) Long-term exposure - inhalation - systemic effects 0.05 mg/m³ (Ind) Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. •Additional information: - • The lists valid during the making were used as basis. <t< td=""><td>(</td><td></td></t<>	(
1(1):AGS,X,10 *alveolengängig *einatembar; als Be •DNELs DNELs for OSH purposes In Germany, occupational exposure limits (AGW) of the Technical Rules on Hazardous Substances (TRGS) 9 continue to constitute workplace aconcentration (MAK value) of the German Research Foundation (DFG) b available, the employer must also consider the DNEL during risk assessment. (Source: Institut für Arbeitsschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available: http://www.dguv.de/ifa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects Inhalative Long-term exposure - inhalation - systemic effects Inhalative Long-term exposure - inhalation - systemic effects O.5 mg/m³ (Ind) Long-term exposure - inhalation - systemic effects Inhalative Inter exposure - inhalation + systemic effects Compliance with the general dust limit value(
DNELs for OSH purposes In Germary, occupational exposure limits (AGW) of the Technical Rules on Hazardous Substances (TRGS) 9 continue to constitute workplace atmospheric limit values that are binding upon employers. Should no AGW a for example no maximum workplace concentration (MAK value) of the German Research Foundation (DFG) b available, the employer must also consider the DNEL during risk assessment. (Source: Institut für Arbeitsschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available: http://www.dguv.de/ifa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects OD5 mg/m³ (Ind) Long-term exposure - inhalation - systemic effects OCompliance with the general dust limit value(s) (ung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. •Additional Information: - The lists valid during the making were used as basis GESTIS International Limit Values: http://www.dguv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanze limit-values-for-chemical-agents/index.jsp 9.2 Exposure controls Personal protective and htgleinc measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective colding separately. Do not eat, drink, smoke or sniff while working. Breathing mask, apparatus with particle filter P2 or P3, for example: - Ful face mask (EN 136) - Breathing mask (EN 136) - B	AGW (Germa	
In Germany, occupational exposure limits (AGW) of the Technical Rules on Hazardous Substances (TRGS) 9 continue to constitute workplace atmospheric limit values that are binding upon employers. Should no AGW a for example no maximum workplace concentration (MAK value) of the German Research Foundation (DFG) b available, the employer must also consider the DNEL during risk assessment. (Source: Institut für Arbeitsschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available: http://www.dguv.de/ifa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects 0.05 mg/m³ (Ind) Long-term exposure - inhalation - systemic effects 0.05 mg/m³ (Ind) Cong-term exposure - inhalation - systemic effects 0.05 mg/m³ (Ind) Long-term exposure - inhalation - systemic effects 0.05 mg/m³ (Ind) Compliance with the general dust limit values for possible hazards during processing: Compliance with the general dust limit values (S) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 5. 4. 5. 4. 5. 4. 5. 4. 5. 4. 5. 4. 5. 4. 5. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4.	-	
 continue to constitute workplace atmospheric limit values that are binding upon employers. Should no AGW a for example no maximum workplace concentration (MAK value) of the German Research Foundation (DFG) bavailable, the employer must also consider the DNEL during risk assessment. (Source: Institut für Arbeitsschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available: http://www.dguv.de/ifa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects 0.05 mg/m³ (Ind) - dottional Cccupational Exposure Limit Values for possible hazards during processing: Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. Additional information: The lists valid during the making were used as basis. GESTIS International Limit Values: http://www.dguv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzer limit-values-for-chemical-agents/index.jsp 2. Exposure controls Personal protective equipment: Ceneral protective equipment: Ceneral protective equipment: Ceneral protective equipment: Vash hands before breaks and at the end of work. Store protective clothing separately. D not eat, drink, smoke or suff while working. Respiratory protection: Inte case of dust formation (limit value exceeded), breathin		
available, the employer must also consider the DNEL during risk assessment. (Source: Institut für Arbeitsschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available: http://www.dguv.de/ifa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects Long-term exposure - inhalation - systemic effects Compliance with the general dust limit values for possible hazards during processing: Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. • Additional information: - The lists valid during the making were used as basis. - GESTIS International Limit Values: http://www.dguv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanze limit-values-for-chemical-agents/index.jsp • 8.2 Exposure controls • Personal protective equipment: General protective equipment: General protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. • Respiratory protection: imit in the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: - Full face mask (EN 136) - Breathing mask, (EN 149) FFP2 or FFP3 10 times the limit value (FFP3) Recommendation: P3 • Protection of hands: • Fortection of hands:	continue to c	onstitute workplace atmospheric limit values that are binding upon employers. Should no AGW an
(Source: Institut für Årbeitsschutz der Deutschen Gesetzlichen Unfallversicherung (IFA)) current values are available: http://www.dguv.de/ifa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects Long-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind) • Additional Occupational Exposure Limit Values for possible hazards during processing: Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. • Additional information: • The lists valid during the making were used as basis. • GESTIS International Limit Values: http://www.dguv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzer limit-values-for-chemical-agents/index.jsp • 8.2 Exposure controls • Personal protective equipment: • General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. • Respiratory protection: • Respiratory protection: • Fuel face mask (EN 136) • Breathing mask, apparatus with particle filter P2 or P3, for example: • Full face mask (EN 136) • Breathing mask, apparatus with particle filter P2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP2) Recommendation: P3 • Protection of hands: • Protection of hands:		
current values are available: http://www.dguv.de/ifa/gestis/gestis-dnel-liste/index.jsp. 7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects 0.05 mg/m³ (Ind) Long-term exposure - inhalation - systemic effects 0.05 mg/m³ (Ind) • Additional Occupational Exposure Limit Values for possible hazards during processing: Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. • Additional information: • The lists valid during the making were used as basis. • GESTIS International Limit Values: http://www.dguv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzer limit-values-for-chemical-agents/index.jsp •8.2 Exposure controls Personal protective equipment: •General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. Respiratory protection: In the case of dust formation (limit value exceeded), breathing apparatus must be worn.	available, the	employer must also consider the DNEL during risk assessment.
7440-02-0 nickel Inhalative Long-term exposure - inhalation - local effects 0.05 mg/m³ (lnd) Long-term exposure - inhalation - systemic effects 0.05 mg/m³ (lnd) • Additional Occupational Exposure Limit Values for possible hazards during processing: Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. • Additional information: • The lists valid during the making were used as basis. • GESTIS International Limit Values: http://www.dguv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen limit-values-for-chemical-agents/index.jsp • 8.2 Exposure controls • Personal protective equipment: • General protective adh ygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. • Respiratory protection: Image: In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed.<		
Inhalative Long-term exposure - inhalation - local effects 0.05 mg/m³ (Ind) • Additional Occupational Exposure Limit Values for possible hazards during processing: Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. • Additional information: - The lists valid during the making were used as basis. • GESTIS International Limit Values: - Therist is valid during the making were used as basis. • GESTIS International Limit Values: - Therist value of or chemical-agents/index.jsp *2.2 Exposure controls Personal protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. • Respiratory protection: Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) • Breathing mask, Explore FP23 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 • Protection of hands: Fortection of hands:		
Long-term exposure - inhalation - systemic effects 0.05 mg/m³ (Ind) • Additional Occupational Exposure Limit Values for possible hazards during processing: Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. • Additional information: - The lists valid during the making were used as basis. - GESTIS International Limit Values: http://www.dguv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzel limit-values-for-chemical-agents/index.jsp • 3.2 Exposure controls • Personal protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. • Respiratory protection: • Full face mask (EN 136) • Breathing mask, apparatus with particle filter P2 or P3, for example: • Full face mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP2) 30 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 • Protection of hands:		
 Additional Occupational Exposure Limit Values for possible haards during processing: Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. Additional information: The lists valid during the making were used as basis. GESTIS International Limit Values: http://www.dguv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzer limit-values-for-chemical-agents/index.jsp 8.2 Exposure controls Personal protective equipment: General protective elothing separately. Do not eat, drink, smoke or sniff while working. Respiratory protection: Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP2) 30 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 		
Compliance with the general dust limit value(s) (lung penetrating and/or inhalable fraction) must be ensured. The AGW for nickel is to be used only for nickel metal. For thermal processes in the presence of atmospheric oxygen, oxidic nickel compounds must always be assumed and the ERB (TRGS 910) must be applied. • Additional information: - The lists valid during the making were used as basis. - GESTIS International Limit Values: http://www.dguv.de/ifa/Cefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzer limit-values-for-chemical-agents/index.jsp • 8.2 Exposure controls • Personal protective equipment: • General protective equipment: • General protective equipment: • General protective clothing separately. Do not eat, drink, smoke or sniff while working. • Respiratory protection: • In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: - Full face mask (EN 136) - Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 • Protection of hands:	LC	ng-term exposure - inhalation - systemic effects 0.05 mg/m ³ (Ind)
http://www.dguv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzer limit-values-for-chemical-agents/index.jsp 8.2 Exposure controls Personal protective equipment: General protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. Respiratory protection: Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: - Full face mask (EN 136) - Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3		
 limit-values-for-chemical-agents/index.jsp 8.2 Exposure controls Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. Respiratory protection: In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 		formation:
 8.2 Exposure controls Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. Respiratory protection: In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 	- The lists val - GESTIS Inte	formation: d during the making were used as basis. mational Limit Values:
 Personal protective equipment: General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. Respiratory protection: In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 	- The lists val - GESTIS Inte http://www.dg	formation: d during the making were used as basis. mational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen-
 General protective and hygienic measures: Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. Respiratory protection: In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: - Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 	- The lists val - GESTIS Inte http://www.dg	formation: d during the making were used as basis. mational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen-
 Keep away from foodstuffs, beverages and feed. Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. Respiratory protection: In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 	- The lists val - GESTIS Inte http://www.dg limit-values-fe • 8.2 Exposure	formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- er-chemical-agents/index.jsp
 Wash hands before breaks and at the end of work. Store protective clothing separately. Do not eat, drink, smoke or sniff while working. Respiratory protection: In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 	The lists val GESTIS Inte http://www.dg limit-values-fe 8.2 Exposure Personal pro	formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- er-chemical-agents/index.jsp e controls tective equipment:
 Store protective clothing separately. Do not eat, drink, smoke or sniff while working. Respiratory protection: In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 	The lists val GESTIS Inte http://www.dg limit-values-fo 8.2 Exposure Personal prof	formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- er-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures:
 Do not eat, drink, smoke or sniff while working. Respiratory protection: In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 	 The lists val GESTIS Intention of the second se	formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- er-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed.
 Respiratory protection: In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 	 The lists val GESTIS Intention of the second se	formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- er-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work.
 In the case of dust formation (limit value exceeded), breathing apparatus must be worn. Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 	 The lists val GESTIS Intention of the second se	formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- or-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately.
Time limits for wearing must be observed. Breathing mask, apparatus with particle filter P2 or P3, for example: - Full face mask (EN 136) - Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 • Protection of hands:	 The lists val GESTIS Intention (Intertion) Http://www.dg limit-values-fe 8.2 Exposure Personal protection General protection Keep away fr Wash hands Store protection Do not eat, distance 	formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- r-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working.
 Full face mask (EN 136) Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 Protection of hands: 	 The lists val GESTIS Intention (Intertion) B.2 Exposure Personal protogeneral protogen	formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- er-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working.
- Breathing mask (EN 149) FFP2 or FFP3 10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 • Protection of hands:	The lists val GESTIS Intte http://www.dg limit-values-fo 8.2 Exposure Personal prot General prot Keep away fr Wash hands Store protect Do not eat, d Respiratory In the	formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- or-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working. protection: e case of dust formation (limit value exceeded), breathing apparatus must be worn.
10 times the limit value (FFP2) 30 times the limit value (FFP3) Recommendation: P3 • Protection of hands:	 The lists val GESTIS Intraction GESTIS Intraction GESTIS Intraction Mathematical structure 8.2 Exposure 8.2 Exposure 8.2 Exposure 8.2 Exposure 8.2 Exposure 8.2 Exposure 9.1 Composition 9.1 Composition<td>formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- or-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working. orotection: e case of dust formation (limit value exceeded), breathing apparatus must be worn. limits for wearing must be observed. hing mask, apparatus with particle filter P2 or P3, for example:</td>	formation: d during the making were used as basis. ernational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- or-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working. orotection: e case of dust formation (limit value exceeded), breathing apparatus must be worn. limits for wearing must be observed. hing mask, apparatus with particle filter P2 or P3, for example:
30 times the limit value (FFP3) Recommendation: P3 • Protection of hands:	 The lists val GESTIS Intraction GESTIS Intraction Mathematical Stress General proton General	formation: d during the making were used as basis. mational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- r-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working. orotection: e case of dust formation (limit value exceeded), breathing apparatus must be worn. limits for wearing must be observed. hing mask, apparatus with particle filter P2 or P3, for example: face mask (EN 136)
Protection of hands:	 The lists val GESTIS Internet to the second se	formation: d during the making were used as basis. mational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- r-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working. brotection: e case of dust formation (limit value exceeded), breathing apparatus must be worn. limits for wearing must be observed. hing mask, apparatus with particle filter P2 or P3, for example: face mask (EN 136) athing mask (EN 149) FFP2 or FFP3
• Protection of hands:	 The lists val GESTIS Internet http://www.dg limit-values-for 8.2 Exposure Personal protogeneral pro	formation: d during the making were used as basis. imational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- ir-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working. brotection: e case of dust formation (limit value exceeded), breathing apparatus must be worn. limits for wearing must be observed. hing mask, apparatus with particle filter P2 or P3, for example: face mask (EN 136) athing mask (EN 149) FFP2 or FFP3 mes the limit value (FFP2)
	 The lists val GESTIS Internet http://www.dg limit-values-fe 8.2 Exposure Personal protection General protection Gene	formation: d during the making were used as basis. rrational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- r-chemical-agents/index.jsp e controls tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working. brotection: e case of dust formation (limit value exceeded), breathing apparatus must be worn. limits for wearing must be observed. hing mask, apparatus with particle filter P2 or P3, for example: face mask (EN 136) athing mask (EN 149) FFP2 or FFP3 mes the limit value (FFP2) mes the limit value (FFP3)
Avoid repeated and prolonged contact with the skin, use protective gloves.	 The lists val GESTIS Intention (1997) Market (1997) The lists val GESTIS Intention (1997) Store (1997) General protocols (1997) General pr	formation: d during the making were used as basis. rrational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- rr-chemical-agents/index.jsp econtrols tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working. brotection: e case of dust formation (limit value exceeded), breathing apparatus must be worn. limits for wearing must be observed. hing mask, apparatus with particle filter P2 or P3, for example: face mask (EN 136) athing mask (EN 149) FFP2 or FFP3 mes the limit value (FFP2) mes the limit value (FFP3) oommendation: P3
	 The lists val GESTIS Intention (1997) Market (1997) The lists val GESTIS Intention (1997) Store (1997) General protocols (1997) General pr	formation: d during the making were used as basis. rrational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen- rr-chemical-agents/index.jsp econtrols tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working. brotection: e case of dust formation (limit value exceeded), breathing apparatus must be worn. limits for wearing must be observed. hing mask, apparatus with particle filter P2 or P3, for example: face mask (EN 136) athing mask (EN 149) FFP2 or FFP3 mes the limit value (FFP2) mes the limit value (FFP3) oommendation: P3
	The lists val GESTIS Inte http://www.dg limit-values-fo 8.2 Exposure Personal prof General prof General prof Keep away fr Wash hands Store protect Do not eat, d Respiratory In the Time Brea - Full - Bre 10 t 30 t Rec	formation: d during the making were used as basis. rrational Limit Values: uv.de/ifa/Gefahrstoffdatenbanken/GESTIS-Internationale-Grenzwerte-für-chemische-Substanzen rr-chemical-agents/index.jsp econtrols tective equipment: ective and hygienic measures: om foodstuffs, beverages and feed. before breaks and at the end of work. ve clothing separately. ink, smoke or sniff while working. brotection: e case of dust formation (limit value exceeded), breathing apparatus must be worn. limits for wearing must be observed. hing mask, apparatus with particle filter P2 or P3, for example: face mask (EN 136) athing mask (EN 149) FFP2 or FFP3 mes the limit value (FFP2) mes the limit value (FFP3) oonmendation: P3



- E ·



Printing date 09.01.2019

- -

for articles

Version number 2

Revision: 09.01.2019

(Contd. of page 4)

Trade name: THERMELAST [®]4290

Preventive skin protection by use of skin-protecting agents is recommended.

Material of gloves

Experience has shown glove materials polychloroprene, nitrile caoutchouc, butyl caoutchouc, fluoride caoutchouc and polyvinylchloride to offer sufficient protection.

- · Penetration time of glove material -
- Eye protection:

In the event of larger quantities of dust: Wear protective glasses / EN 166, poss. with side protection.

· Limitation and supervision of exposure into the environment The legal issue values and limitations are to be paid attention!

SECTION 9: Physical and chemical properties

 9.1 Information on basic physical and chemical properties General Information • Appearance: Form: Semi-finished products/parts: e.g. strip, wire, parts and bars Colour: Metallic • Odour: Odourless • pH-value: Not applicable. Change in condition Melting point/Melting range (approx.): 1,300-1,500 °C • Auto-ignition temperature: Not applicable • Explosive properties: Not applicable • Vapour pressure: Not determined. • Density (approx.) at 20 °C: 8.2 g/cm3 Relative density Not determined. · Solubility in / Miscibility with water: Insoluble. 9.2 Other information No further relevant information available.

SECTION 10: Stability and reactivity

- 10.1 Reactivity No further relevant information available.
- 10.2 Chemical stability
- Thermal decomposition / conditions to be avoided: No decomposition if used according to specifications.
- 10.3 Possibility of hazardous reactions
- Hydrogen is released in contact with acid which can cause explosive gas mixtures.
- 10.4 Conditions to avoid No further relevant information available.
- 10.5 Incompatible materials: No further relevant information available.
- 10.6 Hazardous decomposition products: No dangerous decomposition products known.

(Contd. on page 6)



for articles

Version number 2

Revision: 09.01.2019

Trade name: THERMELAST [®]4290

(Contd. of page 5)

SECTION 11: Toxicological information

•11.1 Information on toxicological effects

• Acute toxicity Based on available data, the classification criteria are not met.

• LD/LC50 values:

7440-02-0 nickel

Oral LD50 >9,000 mg/kg (rat)

7440-41-7 beryllium

Inhalative LC50/4 h ≤0.25 mg/l (rat)

für Aerosole oder Stäube

Primary irritant effect:

- Skin corrosion/irritation see sensitization
- Serious eye damage/irritation

Irritation of the eyes in the case of massive direct contact will be mainly due to mechanical effects depending on the grain size.

- Respiratory or skin sensitisation May cause an allergic skin reaction.
- Germ cell mutagenicity Based on available data, the classification criteria are not met.
- Carcinogenicity
- May cause cancer by inhalation.
- Reproductive toxicity Based on available data, the classification criteria are not met.
- STOT-single exposure Based on available data, the classification criteria are not met.
- STOT-repeated exposure
- Causes damage to organs through prolonged or repeated exposure.
- Aspiration hazard Based on available data, the classification criteria are not met.

SECTION 12: Ecological information

- 12.1 Toxicity
- Aquatic toxicity: No further relevant information available.
- 12.2 Persistence and degradability No further relevant information available.
- •12.3 Bioaccumulative potential No further relevant information available.
- 12.4 Mobility in soil No further relevant information available.
- Additional ecological information:
- General notes: Alloys in solid form do not pose an ecological threat.
- 12.5 Results of PBT and vPvB assessment
- PBT: Not applicable.
- vPvB: Not applicable.
- 12.6 Other adverse effects No further relevant information available.

SECTION 13: Disposal considerations

- 13.1 Waste treatment methods
- Recommendation Observe offical regulations.
- Uncleaned packaging: Not applicable

(Contd. on page 7)



Printing date 09.01.2019

0

for articles

Version number 2

Revision: 09.01.2019

Trade name: THERMELAST [®]4290

(Contd. of page 6)

SECTION 14: Transport information

• Transport/Additional information:

• Land transport ADR/RID (cross-border):

• Remarks: Non-hazardous goods from the standpoint of the specified regulations

Maritime transport IMDG:

• Remarks: Non-hazardous goods from the standpoint of the specified regulations

• Air Transport ICAO-TI and IATA-DGR:

• Remarks: Non-hazardous goods from the standpoint of the specified regulations

SECTION 15: Regulatory information

15.1 Safety, health and environmental regulations/legislation specific for the substance or mixture

Directive 2012/18/EU

- Named dangerous substances ANNEX I None of the ingredients is listed.
- REGULATION (EC) No 1907/2006 ANNEX XVII Conditions of restriction: 27
- National regulations:
- Other regulations, limitations and prohibitive regulations

e.g.

- 1272/2008/EG (CLP)
- 1907/2006/EG (REACH)
- German Hazardous Substances
- 15.2 Chemical safety assessment: Void (for articles)

SECTION 16: Other information

This information is based on our present knowledge. However, this shall not constitute a guarantee for any specific product features and shall not establish a legally valid contractual relationship.

Relevant phrases

Wording of the hazard warnings mentioned (Chapter 3) for pure substances:

H301 Toxic if swallowed.

H315 Causes skin irritation.

- H317 May cause an allergic skin reaction.
- H319 Causes serious eve irritation.
- H330 Fatal if inhaled.

H335 May cause respiratory irritation.

H350i May cause cancer by inhalation.

H351 Suspected of causing cancer.

H372 Causes damage to organs through prolonged or repeated exposure.

• Department issuing SDS:

Department OPS-C SE Tel. 06181/38-2045

• Contact:

Environmental Protection Department Tel. 06181/38-2359

Abbreviations and acronyms:

ADR: Accord européen sur le transport des marchandises dangereuses par Route (European Agreement concerning the International Carriage of Dangerous Goods by Road)

IMDG: International Maritime Code for Dangerous Goods IATA: International Air Transport Association

EINECS: European Inventory of Existing Commercial Chemical Substances

ELINCS: European List of Notified Chemical Substances

(Contd. on page 8)



for articles

Version number 2

Revision: 09.01.2019

(Contd. of page 7)

Trade name: THERMELAST [®]4290

CAS: Chemical Abstracts Service (division of the American Chemical Society) DNEL: Derived No-Effect Level (REACH) LC50: Lethal concentration, 50 percent DD50: Lethal dose, 50 percent PBT: Persistent, Bioaccumulative and Toxic vPvB: very Persistent and very Bioaccumulative Acute Tox. 3: Acute toxicity – Category 3 Acute Tox. 2: Acute toxicity – Category 2 Skin Irrit. 2: Skin corrosion/irritation – Category 2 Eye Irrit. 2: Serious eye damage/eye irritation – Category 2 Skin Sens. 1: Skin sensitisation – Category 1 Carc. 1B: Carcinogenicity – Category 1B Carc. 2: Carcinogenicity – Category 2 STOT SE 3: Specific target organ toxicity (single exposure) – Category 3 STOT RE 1: Specific target organ toxicity (repeated exposure) – Category 1

